

Fig. 1A




Fig. 1 b

gasket without grill
2007-05-23 12:00T




Figure 2

20610" S298200T
effect of hole size




Figure 3

205 F20" S298Z00T

11

microphone with cloth




Figure 4